The following tables give the pin assignments for SL1 and SL2. Side A of the connector are pin outs on the board's component side while Side B are pin outs on the board's solder side. Jumpers JL1 and JL2 give more information on settings on the mainboard and the VL-bus controller.

JUMPER	PIN DEFINITION
JL1	High Speed Write Select 1-2 Zero wait write (default) 2-3 One wait write
JL2	CPU Speed Select 1-2 $\leq$ 33MHz (default) 2-3 > 33MHz