

### CPU Clock VIA (JK1 - JK4)

CLK	JK1	JK2	JK3	JK4
25 MHz	2-3	1-2	2-3	1-2
33.3 MHz	2-3	2-3	1-2	1-2
40 MHz	1-2	1-2	2-3	1-2
50 MHz	2-3	1-2	2-3	2-3

*Table 2-3. CPU Clock VIA Jumper Selection (JK1 - JK4)*

## Connectors

The connectors allow the mainboard to connect electronically with other parts of the system. Some connectors have two pins, others have four or five pins. Some malfunction problems encountered with your system may be caused by loose or improper connections. Ensure that all connections are in place and firmly attached.

CONNECTOR	PIN OUTS	SIGNAL NAME
CN1 PS/2 Keyboard Connector	1 2, 6 3 4 5	Keyboard data NC Ground + 5V Keyboard clock
CN2 PS/2 Mouse Connector	1 2 3 4 5	Mouse data NC Ground + 5V Mouse clock
CN4 Power Connector	1 2, 10, 11, 12 3 4 5, 6, 7, 8 9	Power good + 5V + 12V - 12V Ground - 5V

*Table 2-4. Connector Pin Definitions (Continued)*